



Figure 1. The peak sensitivity for the common elements, using EDS. Alpha K-peaks are indicated. Of the many L and M peaks, only the main peak is shown. Fitting this data would be very difficult, if not useless/inane.